# Bill Acceptor, Find Codes

**Overview:** To find the symptoms for Bill Acceptors diagnostic LED

**Tools Needed:** None

---

**Step 1:** Locate the rear of the Bill Acceptor, a common configuration is depicted below



Bill Acceptor

**Step 2:** To Remove the bill box, push the lock tab (below, left) forward on the top of the box and slide the box up (below, right)



Lock tab, rear view

Lock tab, side view

Bill Acceptor, rear view

# Bill Acceptor, Find Codes

**Overview:** To find the symptoms for Bill Acceptors diagnostic LED

**Tools Needed:** None

---

**Step 3:** Revealed is an index of the flashing patterns of the Diagnostic LED



**Flash Codes**

**1 - Bill box full :** Pull bill cover open and remove bills

**3 - Check bill path :** Possible blockage in bill path

**4 - All bill accept switches OFF :** Check the dip switches located on the circuit board for the Bill Acceptor

**5 - Check optical sensors :** Possible debris in bill path

**6 < Reset or service required :** If normal operation is not achieved on reset, send to Range Servant for service

Range Servant
3000 Center Place, Suite 300
Norcross, Georgia 30093

**Step 4:** To remove the bottom of the bill acceptor, look underneath as indicated below and depress the button while pulling the black "flash codes" box out away from the door